

Government Of West Bengal Office Of The Divisional Fire Officer,Bankura West Bengal Fire & Emergency Services Purulia Fire Station, Ranchi Road,Purulia, Pin:- 723101

Memo no.:IND/WB/FES/20192020/69563 Date: 26-05-2023

From:

Divisional Fire Officer, Bankura
West Bengal Fire & Emergency Services

To: SALTORA BED COLLEGE
PLOT NO- 427/2178, 427/2179, J.L- NO- 108, MOUZA SALTORA, VILLAGE- SALTORA, P.O- SALTORA, P.S-SALTORA, DIST- BANKURA, BANKURA F.S., SALTORA PS, BANKURA-722158

Sub: RENEWAL OF THE FIRE SAFETY CERTIFICATE FOR THE OCCUPANCY OF AN EXISTING G+1 STORIED BUILDING UNDER GROUP EDUCATIONAL ,NAME AND STYLE AS SALTORA B ED COLLEGE AT- PLOT-427/2178,427/2179,J L-108.MOUZA- SALTORA,VILL,POST&PS- SALTORA, DIST- BANKURA, PIN-722158.

This is in reference to your application no. 0125191237800064 dated 16-05-2023 regarding the RENEWAL OF THE FIRE SAFETY CERTIFICATE FOR THE OCCUPANCY OF AN EXISTING G+1 STORIED BUILDING UNDER GROUP EDUCATIONAL ,NAME AND STYLE AS SALTORA B ED COLLEGE AT- PLOT-427/2178,427/2179,J L-108.MOUZA-SALTORA,VILL,POST&PS- SALTORA, DIST- BANKURA ,PIN-722158.

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found satisfactorily working condition. In view of the above this office is releasing the Renewal of Fire Safety Certificate for occupancy of the aforesaid building.

However to up-keep the Fire Safety Measure of the aforesaid building the following safety measures need to be incorporated / maintained.

Recommendation:

RECOMMENDATION

The performance of the firefighting system as incorporated into the building was tested at random and found satisfactory working conditions. Given the above, this office is releasing the Fire Safety Recommendation for occupancy of the aforesaid building. However, to up-keep the fire safety measure of the aforesaid building the following safety measures need to be incorporated /maintained.

1. Driveway must be free of any type of obstruction for easy movement of fire appliances. No parking will be allowed on the

driveway.

- 2. To eliminate the risk of fire hazards, good housekeeping both inside and outside of the building s2hall be strictly maintained.
- 3. Existing electrical wiring of the whole building shall have to be carefully checked for any were and tear in them, particularly lines above false ceilings.
- 4. Afire control room including a closed-circuit TV system will have to be maintained which observe all floor of the building.
- 5. The notice of firefighting and evacuation plan from the building shall be prepared and displayed at all suitable places in the building.
- 6. The employees and security staff shall be conversant with the installed firefighting equipment of the building and to operate in the event of fire and testing.
- 7. Mock fire practice and evacuation drills shall be performed periodically with the participation of all occupants of the building.
- 8. Transformer and switchgear room shall be protected with an automatic CO2 or DCP fire extinguisher conforming to I.S. specifications.
- 9. Arrangements shall be made for regular checking, testing, and proper maintenance of all the fire safety installation and equipment installed in the building to keep them in perfectly good Working conditions at all times.
- 10. The fire safety audit is to be conducted a regular intervals and to be recorded in the fire prevention maintenance register.
- 11. Fire notice for firefighting and evacuation from the building shall be prepared and displayed at all vulnerable places of the building.

12.. This Fire Safety Certificate has a validity of 03 years and have to be renewed on each end of every three years.

Signature val

Divisional Fire Officer.Bankura West Bengal Fire & Emergency Services

The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the 'Verification of Digitally Signed Document' link and keying in the Unique Number: 0125191237800064.

Page: 2